

# Product Safety Recall



## Black Nylon Fuel Filler – 160400

Black Nylon Fuel Filler that was installed to some boats manufactured and/or despatched by Telwater Pty Ltd between 10<sup>th</sup> July 2017 and 14<sup>th</sup> Nov 2017. These boats were sold through Quintrex, Stacer & Savage Dealers nationally. A list of potentially affected serial numbers is available.

**DEFECT** In some circumstances water entry into the fuel tank is possible via the breather holes.

**HAZARD** If water enters the engine's fuel system via the fuel tank the engine could shut down, rendering the boat unable to return to port under its own propulsion and increasing the risk of an accident and/or injury to the boat occupants.

**WHAT TO DO** Consumers should immediately stop operating the boat and engine and contact their nearest Telwater dealer to have the fuel tank inspected and fuel filler spacer installed.

**CONTACT DETAILS** You can locate your nearest Telwater dealer by going to :

[www.quintrex.com.au](http://www.quintrex.com.au)

[www.savageboats.com.au](http://www.savageboats.com.au)

[www.stacer.com.au](http://www.stacer.com.au)

[www.telwater.com.au](http://www.telwater.com.au)

or by phoning Telwater on (07) 5585 9898 Mon-Fri 8-4:30pm, or via email at [recall@telwater.com.au](mailto:recall@telwater.com.au)

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**